## Assessment of Performance of Carbon Brushes

### **Commutator Appearance**

In addition to the physical appearance of the surface of the commutator, the skin or patina is of

equal importance for the good running of the carbon brushes. Each carbon brush builds a characteristic patina which is affected by operating and ambient conditions. The patina consists mainly of copper oxides, graphite deposits and adsorbed water, and its appearance is of importance when assessing the most suitable brush grade. The following pictures show typical appearances of commutation surfaces. The pictures are not of an international standard specification but are used by carbon brush manufacturers and users of brushers as a guide to assist in judging the operation of carbon brushes.

### Normal Skin or Patina Formation



**P2, P4** and **P6** are examples of normal skin or patina formation. When a machine runs well, the patina or skin on a commutator will be even, slightly shiny and coppery brown to black in colour. There may be appearance of greyish, blueish and reddish hues. but of importance is the evenness of the skin formation and not its colour.

# Appearances of Badly Formed Patina or Skin



P12 • Appearance: Streaky patina having some wide and narrow tracks of different colour. No commutator wear Causes: High humidity, oil vapour, aggressive gases in the atmosphere, low electrical load on the brushes



P14 • Appearance: Torn patina, general appearance as in P12, but with narrower tracks and commutator wear Causes: As in P12, but the conditions have been maintained for a longer period causing commutator damage



**P16** • Appearance: Smutty patina, uneven skin having patchy colours and random spots Causes: Uneven commutator or unclean operating conditions



**P22** • Appearance: Patina with dark areas, regular or irregular patches covering one or more commutator segments Causes: Out of round commutator, vibrations of the motor caused by badly adjusted shaft or damaged bearings



**P24** • Appearance: Dark patchy patina having definite edges as in TI2 and T14 Causes: Raised segment or group of segments causing the brush to bounce



**P26** • Appearance: Commutator segments having patches in the middle or at the edges. Causes: Often due to faulty grinding of the commutator



**P42** • Appearance: Alternating light and dark bar markings Causes: Uneven current distribution over two parallel windings caused by double windings crossing in the same slot



**P46** • Appearance: Mat patches in double pole pitches Causes: Usually by faulty soldering of the risers or segment connections

#### **Bar Burning**





**B2, B6, B8.** Appearance: Bar edge burning or burning in the middle of bar Causes: Sparking caused by commutation problems



**B10** • Appearance: Perforated patina, light, dense or distributed build-up spots Causes: Patina destruction caused by too large electrical resistance

#### **Bar Marking**



**T10** • Appearance: Dark patches at edge of bars in direction of rotation Causes: Frequently caused by long periods with the motor being stationary without power or short stationary periods under load



**T12** • Appearance: Burning of a trailing edge and the next leading edge of a bar Causes: Caused by protruding segment as in L2



**T14** • Appearance: Dark markings Causes: Sign of a low segment, could also be caused by a flat spot on the commutator (see L4)



**T16** • Appearance: Clearly defined dark markings together with segment edges burnt Causes: Raised mica (see L6)



**T18** • Appearance: Dark markings Causes: Badly undercut segment edges (see L8)



- **L2** Protruding segment
- **L4** Low segment

L6 • Raised mica

**L8** • Ridge on the segment edge Causes: Faulty commutator segments

**L10** • Copper drag Causes: Bumps or vibrations from various causes

### Appearance

## of the Brush Sliding Face

The following pictures show typical brush-sliding faces. For easy identification we suggest you use the symbols **S1, S3** etc. S1, S3 and S5 are satisfactory sliding faces, indicating that there are no mechanical or electrical problems. Depending on the carbon material the sliding surface appears dense or porous, and shiny dull or matt. If there is dust in the circulating air fine hairlining may occur as shown in S5.





**S9** • Tracking with hairlining and groves

Causes: Like S7, but stronger



 $\begin{array}{l} \textbf{S11} \bullet \textbf{Ghostmarks, difficult commutation} \end{array}$ 

Causes: Commutation problems, e.g. false or incorrect position of the neutral zone or interpole



**S13** • Burning edge of the leaving or trailing edge

Causes: Difficult commutation, heavy sparking, interruption of contact due to out of round of commutator or insufficient brush holder spring pressure



S15 • Eroded brush face

Causes: Electrical overload, interruption of contact

S17 · Lamination of sliding face Causes: Burned segments of the

commutation







**S21** • Copper nests

**S19 •** Double facing here for a twin brush

# Causes: Tilting of the brush in dual direction machine

sliding face caused by a winding fault giving voltage surge during

Causes: Pick up of copper particles, often following copper drag



S23 • Broken edges

Causes: High raised lamination, commutator seriously out of round, brush chatter